


0-180° fittings

Fitting at an angle of up to 180°. The fitting is used where the machine guard needs to be set up at angles other than 90°.



Models

ARTICLES / DESCRIPTION



T01-01
Fittings for creating corners up to 180°