


MOUNTING INSTRUCTIONS

MOUNTING X16





120-320



X62 x2

X61 x2




X1 x2



X62 x2



X61 x2

420-620



X62 x2

X61 x2



X1 x2



X62 x2

X61 x2